

IEM 10
Lower Nahiku Bridge Health and Safety
Concerns

RECEIVED AT IEM MEETING ON 2/1/16
PW Deputy Director

Location Map

Red: State
Tan: Private








PHOTO 1 4x12 DECK PLANKS AND METAL GUARDRAILS ON BRIDGE



PHOTO 2 MAKAI SPAN



PHOTO 3 MAUKA SPAN



PHOTO 4 6x12 TIMBER GIRDERS LAPPED OVER INTERMEDIATE PIER



PHOTO 5 TIMBER PIER BETWEEN THE MAUKA AND MAKAI SPANS



PHOTO 6 CONCRETE PIER WALL